INOR

QUICK START INSTRUCTIONS FOR INOR USB SOFTWARE INSTALLATION

Follow these simple instructions for a successful install

- ***Do not plug in the cables to your laptop or PC***- 1st install the software (Drivers could go in wrong- but this can be fixed).
- Follow the sequence, steps 1 and 2, shown in the below window. Then install the application software, like IPRO 4.32 or MinIPAQ SOFT 1.24.
- Plug the interface cable and interface into the PC. Confirm that new hardware is found and installed.
- Plug in the transmitter (and if IPAQ-H/ L; IPAQ-4L; or any other TX that programs with IPRO 4.32) the unit must be powered during configuration. [Except IPAQ=H+ / L+]
- Double click on ConSOFT V2 shortcut on desktop.
- Close instruction box and read from transmitter (ConSOFT is figuring out which application software to open).
- Use the application software to program the transmitter.
- DONE.

INOR Setup

INOR

1 Install USB Interface drivers	Install ProfiSoft 1.2.00
2. Install ConSoft 2.0.0.8	Install Ipro 4.32.00
Install MinIPAQ Soft 1.24.00	Exit