

PROGRAMMING DISPLAY

STEPS	DISPLAY	ACTION	
#1 Main Display Press HOLD		1st. Step Press and Hold Both	<p>4mA Empty</p>
#2 Low Level Value Press 1x	 Low Value - 4mA = 0	2nd. Step Default Preset = 000.0 No need to change Press	
#3 Press 2 sec		3rd Step In this screen press and hold for 2 sec	<p>20mA Full</p> <p>4mA Empty</p>
#4 High Level Value Enter High Level Value	 Enter Max Tank Value	4th Step Change number to Desired value (Note: This value is your max tank level) Inches Gallons Liters	
#5 Press 2 sec to SAVE		5th Step Press 2 sec to SAVE	<p>20mA Full</p> <p>4mA Empty</p>
#6 Return to Main Display Press HOLD		6th Step Press & Hold Return to Main Display	
#7 Main Display	 Current Level Value	Finished Current Tank Level	<p>20mA Full</p> <p>4mA Empty</p>